

Ceramic Ordering Instructions

1. Email us at info@barkerscoating.com with your name, contact information, a picture, description and number of parts to be ceramic coated. We will email you back quickly with a price quote. Color selections can be found on our website at www.barkerscoating.com.
2. Download and print out the Ceramic Order Form available at www.barkerscoating.com. Fill out the entire form including your name (It should be the same name that was used on the quote) personal information, description, color and quote information. Also fill out the desired method of return shipping.
3. Package your parts up securely in a cardboard box so they cannot move around or rub against each other. Include the completely filled out Ceramic Order Form in the box so it can easily be found. It should be right on the top when we open the box. Also include your name and address somewhere on the outside of the box in case the form would get separated from the box during shipping. If you are reusing a previous shipped in box make sure all wording that is not applicable is crossed out with a sharpie.
4. Ship the package to:
Barkers Coating Solutions, LLC
1140 S. State St. Suite 10
Ephrata, PA 17522
For added protection shipping insurance is recommended. Please allow up to 3 weeks for return shipping, depending on the method of shipment. We will contact you once we receive your package.
5. Once we have completed ceramic coating your parts we will contact you concerning payment. Payments made by personal check MUST be sent along with the parts. Once the check has cleared we will return ship the parts back to you. If payment has not yet been made we will call you so payment can be made over the phone by credit card or online via PayPal. Once payment has been made in full the parts will be return shipped. If shipping insurance was paid for it will be added, otherwise the parts will be returned shipped via UPS or USPS Ground. Expedited shipping is available at an additional charge.
6. While the newly ceramic coated parts can be packaged and shipped within 48 hours they cannot be applied to high temperatures for 5 days. Although in most cases this time period would have expired during shipping depending on your location and method of shipping you may receive your parts before this time has expired. This time frame will be clearly marked on your parts when you receive them. Make sure you allow the necessary time before applying them to high temperatures